

CONSTRUCTION OF COMPOUND WALL AT KUNAL ICON HOUSING SOCIETY



Problem:

- There were major cracks in the compound wall and the corporation had sent a notice to the society to repair the wall immediately.
- Many big trees had caused damage to the brick wall and it wasn't possible to cut the trees.

Solution:

- We constructed a brick wall and maintained some gap between the tree and the wall.
- We prepared a ferrous cement thin wall to maintain the external aesthetic view and to maintain the gap between the walls.