

STRENGTHENING OF MILL FOUNDATION AT PELLET PLANT



Problem:

- After erecting a heavy drum, there was some deflection at mill foundation.

Solution:

- Provided an additional pile at the side of this foundation for load distribution.
- Provided Rebaring of the existing mill foundation, to transfer the load to the dowel bar.
- Enlarged the foundation sectional area to divide the load to the newest pile.