

REROUTING OF THE CONVEYOR BELT AT THE DHARAMTAR PORT



Problem:

- The conveyor belt project was in the commissioning phase when there was an issue of the landowner with the client of his land.

Solution:

- We checked the possibility of adding a new additional foundation bolt on this Jetty Deck Slab.
- Hilti prepared design for rerouting with the new bolt.
- We did the core cutting, fixed the anchor bolt and the erection work was started within 8 days.