

CEMENT PRESSURE GROUTING OF THE SPRAY POND AT SHRI SANT TUKARAM SAHAKARI SAKHAR KARAKHANA



Problem:

- There were leakages at the bottom side of the wall at a 20 year old stone masonry.

Solution:

- We fixed the nozzle in the staggered position.
- We used Grout cement slurry to fill the void and fill leakages.